

Схемы главных электрических цепей КСО-298

1BB-630	2BB-630	3BB-630	4BB-630	5BB-630	6BB-630	7BB-630	8BB-630	9-160
10-160	11-160	12-HTMI	13-HTMI	14-KV	15T-63	16T-63		18-HOM
19-HTMI	20-HOM	22-630	23-630	24-1000	25-HTMI	26-630		28A