

Рис. 1 Сетка схем главных цепей камер серии КСО-207

1BB-1000	2BB-1000	3BB-1000	4BB-1000	5BB-1000	6BB-1000	7BB-1000	8BB-1000	9-160
10-160	11-160	12-1000HTMI	13-HTMI	14-KY	15T-63	16T-63		18-1000HOM
19-1000HTMI	20-HOM	22-1000	23-1000	24-1000	25-1000HTMI	26-1000		28A